
E06010 Run Coordinator Report







- Wednesday (10/22) -> Friday (10/24)
 - Beam Delivery Issues (for setup):
 - FSD problem with Target to Beam Dump Vacuum
 - Target Laser Alignment
 - Target Ladder Setup
 - Setup of limit switches at each target position
 - Polarized Target / Solid Targets Installed
 - Finished up Safety Checklist





- Weekend (10/25 10/26)
 - Beam Delivery Issues:
 - Vacuum event in Injector (long pumpdown time)
 - 1H03A HARP stuck. Target OTR foil gone.
 - Target Polarization Low
 - Checked BigBite Steering with Ion Chambers
 - Detector & Trigger checkout with EMPTY target
 - Some discrepancies with redundant scalers
 - RICH/BB-MWDC hardware issues.
 - BPM signals saturated



- Monday (10/27) to Present (10/28)
 - Continued work on:
 - 1H03A HARP
 - Increasing Target Polarization
 - RICH Freon System, RICH DAQ Readout
 - BB-MWDC timing offsets
 - Adjustments of trigger timing and TDC common stops
 - Reference Cell installed & tested.





- Other Pending Issues/Upcoming Events:
 - Ion Chamber Calibration (needs targets)
 - Target Training (Today 4pm)
 - Rich Freon System
 - LHRS collimators need resurveyed
 - 1H03A HARP
 - BTA Software (have temporary fix)






- Other Pending Issues/Upcoming Events:
 - Check of BigBite optimal position
 - Moller Measurement
 - HAPPEX Charge Feedback check
 - LUMI Commissioning






BigBite Steering Test

















Target OTR







Target Enclosure







Target Ladder



ШíГ

