Abbe-Diagram n_e–ν_e

Description of Symbols

- N- or P-glass
- Lead-containing glass
- N-glass and lead-containing glass
- Glass suitable for Precision Molding
- CaF2 and Fused Silica



www.us.schott.com/advanced_optics