

Here is an update of issues discussed on 19 September;

1. EDTM mixer – to be installed in the hall: Barak, Longwu, Kalyan
2. S2m and S0 efficiency for LHRS– concluded: Barak
3. Time walk correction for S2m and S0 was concluded. The timing aspect of G.C was discussed and there were concerns about non-uniform noise in TDC – x plots. : Longwu
4. VDC and FPP – No signal for bottom VDC(it might be a result of no gas flow through the chambers), noisy wire in top. 2 Modules missing in FPP and there were concerns about the drop in the number of active straws : Yang, Mongi
5. GMP website – discussion on how to improve website : Thir
6. Trigger supervisor to be taken to Ed : Kalyan