

RQ2	RQ3	LQ2	LQ3	LD	Pressure Left	Pressure Right	Regulated Pressure Pivot	Delivery Pressure
X	X	X	X	X	235	225	230	218
X	O	X	X	X	130	/ 122	/ 130	218
O	X	X	X	X	130	/ 125	/ 130	218
O	O	X	X	X	130	2 119	2 128	218
X	X	O	X	X	/ 130	125	/ 132	218
X	X	X	O	X	/ 130	125	/ 130	218
X	X	O	O	X	2 125	122	2 128	218
X	X	X	X	O	/ 132	126	/ 132	218
X	X	O	X	O	2 128	123	2 128	218
X	X	O	O	O	3 120	120	3 124	218
O	X	O	O	O	3 120	/ 116	4 120	218
O	O	O	O	O	3 115	2 110	5 118	216
O	O	O	O	X	2 120	2 114	4 120	216
O	O	O	X	O	2 120	/ 114	3 120	216
O	O	X	O	O	2 120	/ 114	3 120	218
O	O	O	X	X	2 125	/ 117	3 124	218
O	O	X	X	O	2 128	/ 117	3 124	218
O	X	O	X	X	/ 130	/ 122	2 128	218
X	O	O	X	X	/ 130	/ 122	2 128	218
X	O	O	X	O	/ 125	2 120	3 124	218
X	O	X	X	O	/ 130	/ 122	2 128	218

All pressures are in PSI. X means the power supply has no flow through it, O means it has full flow through it.