

FERRUPS DB 25
Communication Connector

HMS UPS

Customer Supplied Relay

20 Sep '18
AK




Figure 18 Connection External Signal Relays

- ③ Finder Dose Model 99.01.9.024.99
- ② Finder Dose Model 40.31.9.012.0000
- ① Finder Type 95.63 Relay Socket