



American Hakko Products, Inc.

## P R O D U C T B U L L E T I N

**Bulletin No:** PB151

**Issue Date:** June 12, 2002

**Product:**

FM-202

**Part No:**

FM202-01

FM2021-01

B2765



**Sleeve assembly and connector (with tip)**

**Specification:**

The connector (FM-2021) and sleeve assembly (B2765) have been modified. The connector cover is approximately 10mm longer and the sleeve assembly is approximately 10mm shorter. The part numbers have not changed.

**Comments:**

All FM-202 stations shipped from American Hakko after May 30, 2002 have the new sleeve assembly and connector cover. The shorter sleeve assembly will allow a tip to be inserted into the Process Gate without requiring removal of the sleeve assembly. This will make for faster tip changes.

**Accessories:**

FM-2021R retrofit kits have been delivered to Hakko Representatives to retrofit FM-202 stations shipped prior to the change. The retrofit kit includes a connector cover and sleeve assembly.

**Available:**

May 30, 2002

For pricing information, please contact your local American Hakko representative or our customer service department at (661) 294-0090.

From...

American Hakko Products, Inc.  
28920 N. Avenue Williams.  
Valencia, CA 91355  
Tel: (661) 294-0090  
Fax: (661) 294-0096  
[www.hakkousa.com](http://www.hakkousa.com)  
AHP14 Rev 2000-01