




Typical Cernox™ Resistance




Typical CX-1010 Resistance




Typical CX-1030 Resistance




Typical CX-1050 Resistance




Typical CX-1070 Resistance




Typical CX-1080 Resistance




Typical Cernox™ Sensitivity




Typical CX-1010 Sensitivity




Typical CX-1030 Sensitivity




Typical CX-1050 Sensitivity




Typical CX-1070 Sensitivity




Typical CX-1080 Sensitivity




Typical Cernox™ Dimensionless Sensitivity




Typical CX-1010 Dimensionless Sensitivity




Typical CX-1030 Dimensionless Sensitivity



Typical CX-1050 Dimensionless Sensitivity



Typical CX-1070 Dimensionless Sensitivity



Typical CX-1080 Dimensionless Sensitivity

