LESSONS LEARNED DATA SHEET: HALL-A

Date Identified	By Whom	Description of Action	Things That Went Right	Things That Could Have Been Done Better
*** Please used this highlighted section as an example for filling out the form. ***				
"January 1, 2000" or "January 2000" (Exact date is preferred but month	"Jessie Butler" or "Work Coordinator" (Name is preferred but a	Removed tagged item from RCA (Hall A) without contacting	 The mistake was immediately identified and RADCON was contacted. 	1- The RADCON tag was not clearly displayed on the item.2- The employee felt pressured to
& year is acceptable)	person's title is acceptable)	RADCON first.	2- The person remained with the item until RADCON showed up to provide guidance.	meet deadline. 3- Breakdown in communication between members of the team.
09/23/2020	Robert Tucker	Tool chest was damaged by forklift.	 Nobody was injured because the area was kept clear of personnel. No additional damage was done to other items in the same area. 	 1- Qualified spotter should have been used while operating large forklift (Crusher) in a tight work area. 2- Tool box should have been moved prior to work being started. Better PRE-PLAN

Please use this space to provide additional notes, comments, and suggestions about the action:

Crusher was being used in the hall to take Moller platform outside to be surveyed by radcon. The only on the ground spotter was a radcon tech. While turning the wheel one of the lug nuts pinched into the toolbox. This resulted in the edge of the box becoming damaged.

Future moves with large forklifts in tight spaces should include a qualified tech to spot for the driver.

Preplanning the job should include removing unnecessary items near the area of work.