




GEM Alignment

- New alignments were done after changes made to the setup.
- Results shown are from several days after to show stability.

After SBS-4
(11496)



After replacing resistor
(11595)

