


# DVCS weekly meeting

July 26th, 2010

## Test with cosmics


- ▶ Took data (firmware 13) with 7 boards at a time
- ▶ Whole calorimeter tested
- ▶ Some issues with DAQ (channels get swapt)

# Column 0




Individual blocks


## Column 1




## Column 2




## Column 3



## Column 4




## Column 5






Individual blocks

## Column 6




Individual blocks


## Column 7




## Column 8




## Column 9




## Column 10



## Column 11



## Column 12



# DAQ

- ▶ Working firmware 13. Still same issues as last week:
  - ▶ Boards not responding after a few 10k events
  - ▶ Signal swap between channels within a board



## Plan for the week

- ▶ Moving detector to the Hall on Tuesday/Wednesday
- ▶ Get ready for moving (Monday):
  - ▶ Uncable SHV cables
  - ▶ Uncable 4m signal cables from patch panel
  - ▶ Unstack calorimeter
  - ▶ Uncable DAQ and slow control rack