


Sum8 to ADC (2nd level) Patch Panel Front, changes made on 6/2/09.

These are connected to
(from left) 4th Sum8
input



5
4 means this connector was originally connected to cable "TA 5", and now is connected to cable "TA4", that goes to the 2nd floor ADCs.