


Time walk The TDC and FADC data in same event may not comes from one event, should be some mismatch.




Time resolution after add FADC (caused by the change of TDC trigger input)




Time difference between trigger input and TDC stop(from trigger module busy output)




Time difference of same channel



THU module





FADC spectrum of trigger scintillator

