## **BigBite calorimeter and DAQ update**

- shower test/calibration done all channels are working fine
- scintillator test done all channels working fine
- preshower test done, calibration not finished (waiting for the fastbus power supply)
- FASTBUS readout for the wirechambers is done working fine (see plots in Xin's talk)
- intergration of VME setup with trigger supervisor is done.
- remote threshold setup for the discriminators is working.
- need to finish rest of the front-end logic(OR of SUMs for e- trigger)

## Items needed

- seven 1877(FASTBUS) TDCs
- four 767(VME) TDCs