

4

(COORDINATES IN METERS)

PED. BOLT LOCATION	REF. PT.	COORDINATES		
		Z	X	Y
P11H02-BOLT	A	-375.9738	-46.31110	97.05020
P11H02-BOLT	B	-375.9269	-46.66724	97.05020
P11H02-BOLT	C	-376.2352	-46.52668	97.05020
P21H02-BOLT	A	-375.3625	-45.93172	97.05020
P21H02-BOLT	B	-375.7186	-45.97860	97.05020
P21H02-BOLT	C	-375.5781	-45.67025	97.05020
P31H02-BOLT	A	-378.1032	-44.99728	97.05020
P31H02-BOLT	B	-377.7471	-44.95040	97.05020
P31H02-BOLT	C	-377.8876	-45.25875	97.05020
P41H02-BOLT	A	-377.4919	-44.61790	97.05020
P41H02-BOLT	B	-377.5388	-44.26176	97.05020
P41H02-BOLT	C	-377.2305	-44.40232	97.05020

CARTRIDGE LOCATION	REF. PT.	COORDINATES		
		Z	X	Y
P11H02-CTR_CART	CENTER	-375.7757	-46.19897	99.60451
P11H02-LFT_CART	CENTER	-376.6171	-45.79345	99.60451
P11H02-RT_CART	CENTER	-376.3851	-45.49118	99.60451
P31H02-CTR_CART	CENTER	-376.9999	-45.25960	99.70015
P31H02-LFT_CART	CENTER	-377.5795	-45.07097	99.70015
P31H02-RT_CART	CENTER	-377.3321	-44.74855	99.70015